1913

Friday 1

Saturday 2

1913

Saturday 2

1899

4 heifer

Minor 100 Grass

PAB 30 G

2 heifer

250 Minor
25 PA Blue

Hard Glass

30	SiO_2	15·0
10	CaO	5·0
10	Na_2CO_3	5·0
50	Flint Black	25·0

1 Black	5 Grms	10
Oxide	5·0	100

not enough color

added 200 Grms.

Thereon too much lead + black

1913

Sunday 2

100R

400 g below
10 $PbSO_4$
4 Borax

150 S
8 P
25 — NaH
65 — Nav
H $BaCO_3$
H Borax
½ B_2O_3
H CaO

Pomona

	350	
SiO_2	~~300~~	150
Pb_3O_4	50	3
$NaNO_3$	50	25
Na_2CO_3	100	65
$BaCO_3$	8	4
MnO	3	1½
CaO	9	4½
		348

SiO_2	150	Try a Nagel
Pb_3O_4	8	
Na_2CO_3	65	
$NaNO_3$	25	
$BaCO_3$	4	
MnO	1½	
CaO	4	

1913

Monday 263 4

Pomona 213

100 g Batch acid
20 " Hig Bbl

---

too Green
added 20 g H. Bbl

Grew Pomona

260 Grew Called

260. Plant Bch.

1913

Tuesday 5

1813

added to below —

SiO_2	134 =	270
Na_2CO_3	68.4	135.8
$CaCO_3$	23.2	46.4
Al_2O_3	7.50	13.0
Borax	2.0	4.0

+ 200 g MnO_2
30" Bl

Too hard [illegible]
& added. 50 Na_2CO_3
15 $NaNO_3$

Soda Glass

			P.G. %
SiO_2	67.0	70	= 57.50
Na_2CO_3	29.0	35	24.70
$CaCO_3$	9.6	10	8.25
CaF_2	1.6	$1\frac{1}{2}$	1.23
Al_2O_3	8.3	8	6.60
B_2O_3	2.0	2	1.65

Melted in small pot-
11 to 12 1 30

altered added

SiO_2 20
Na_2CO_3 10
$CaCO_3$ 8

1913

Wednesday 6

1915

Hudnut 5/ar. Pb_3O_4

SiO_2 · 365

Pb_3O_4 80

Na_2CO_3 ~~117~~ – 120

$NaNO_3$ 20

Borax 4.

Sel. ·60

Co_2O_3 ·10

· Good color dragged & melted again with ·60 Sel

Hard to melt properly.

1913

Thursday See over 7

added as under

SiO_2	182½	547½
Pb_3O_4	40	120
Na_2CO_3	90	210
Na_2HO_3	15	35
$Borax$	2.	6
Sel		Gum 1'10
CoO		" '10
Cu_2O_3	10	'10

Thus mixed as

was a good Color but hard to melt. some seeds.

Regular Hand-work Sel.

	Lbs.	
SiO_2.	1820	
Pb_3O_4	980	
Na_2CO_3.	600	
$NaNO_3$	100	
Ca_3PO_4	3	
As_2O_3	1	Gram
Sel.		-6.25-
Co_2O_3		.10

Very good color wants a little more say ~~12.25~~ 60.00

1913

Friday

Alab. yellow
+ match dome lights

100 alab
5 clay
2 crucible
1 oz U_3O_8 OK.

1913

Saturday 0

Soda Glass Flux:

SiO_2	61.00	= 305.00
Na_2CO_3	25.50	127.50
$NaNO_3$	5.00	25.00
$CaCO_3$	7.20	36 00
Borax	.75	3.75
As_2O_3	.50	2.75

1913

Sunday 10

1

Btch 90

Iron Scales - 10

2

Btch 90

Iron Scales 10

Cu-04 1

246.

Btch	90
$FeSO_4$	10
Tartar	1
Carbon	1

247

Btch	92.	460.00
Cerium	6.30	31.50
$Th O$	.04	.20
Fe_2O_3	1.60	8.00
Cr_2O_4	.06	.30

1913

Monday 1 1

[illegible]

2448

Btch	94.80
Cem	4.72
Li_2O	.30
Na_2O	.30
$CoSO_4$	.08

1913

Tuesday 12

150

Blck 90

Cem 8.13.

Nickel Sulphate .07

H2O 1.50

158

Blck 89.75

Cem 8.13.

Fe2O3 2.08

P2O5 .09

1913

Wednesday 12

1913

Decolorizer

2 lbs of Sel
1 or 2 Cobalt.

use 4½ oz of above to
1 lb of Charcoal. to
1000 SiO2.

1913

Thursday 1 1

Etching paste

No 1 1½ Oz. Ammonium flouride

1. H.F.

No 2. 4 Oz Gum Adragacanth Powder

4" Ammonia Liquid.

4" Water

½" Lamp Black.

Mix well in Tin Box

and Boil in Water ½ hour.

---

over

1913

Friday 1 5

No 3

4 ozs of No 1.

2" Magnesia Carbonate

1" Starch

1/2 No 2.

Mix well. Use on plates for prints.

1913

Saturday 1 6

Polishing

5 lb of H_2SO_4
1 " H_2O.
1/2 HNO_3
1/2 H.F.

Frosting Bath.

3 lbs Am. Fluoride
2 " H.F.
let stand 1 Hour.
Take off Clear Solution.
2 ~~pints~~ pints
1 ~~pint~~ Soda in Cups washing
2 or. White Lead,

Sunday 1913 17

SiO_2 302

K_2CO_3 50 any by

$PbSO_4$ 193

HNO_3 24

As_2O_3 .500

B_2O_3

1913

Monday 10

Soda Btch.

SiO_2	305.00
Na_2CO_3	127.50
$NaNO_3$	25.00
$CaCO_3$	37.50
Borax	3.75
As_2O_3	2.75

1913

Tuesday 10

360
2
720 360
5
720
260
2
520
110
30

Crookes 91B. C.S.N.

SiO_2	366 = 365	
Na_2CO_3	153 - 150	
$NaNO_3$	30	
$CaCO_3$	60 = 50	
$Cr\ Ox$	35	= 1/2 g light col.
Borax	4	1/2 " dark "
As_2O_3	3	
	648.	

Cl Na_2CO_3 100
25 1/2 $NaNO_3$ 73
5
8
5 3/4 =
.662
.5

1913

Wednesday 20

92 ©

SiO_2	360
Na_2CO_3	150
$NaNO_3$	30
$CaCO_3$	45
Borax	5
As_2O_3	2
100	35
CoO	3/4 oz
NiO	13 oz
Li_2O	12 oz

Acid Crucible

Crookes. 91 C.

for Sealing to Flint.

SiO_2	325
Na_2CO_3	115
$NaNO_3$	25
$CaCO_3$	65
Cer Ox	30
Feldspar	28

1913

Thursday 2.1

230

.45

2

90

95

2

190

Fuerza Green

	45-D.	45-C	45-A.
SiO_2	345-	345-	345-
Na_2CO_3	115-	115-	115-
$NaNO_3$	25-	25-	25-
$CaCO_3$	95-	95-	95-
Feldspar	30	30	30
As_2O_3	1	1	1
Rutile	8	8	8
Sodium Chromate	6 oz	10 oz	2 lb
Nr_2O	1 oz	1 oz	4 oz

1913

Friday 22

Golden Amber.

	33F.	33E -	33D.
SiO_2	365	365	365
Na_2CO_3	140	140	140
$CaCO_3$	95	95	95
Rutile	8	8	8
Carbon.	1/2	1/2	1/2

33E

SiO_2	—	345	—
Na_2CO_3	—	135	—
$CaCO_3$	—	95	—
Feldspar	—	30	—
Rutile	—	8	—
Carbon	—	2.	—

1913

Saturday 22

1913

39.T. Norwield

SiO_2 138 No 6 Shade.
Na_2CO_3 30
Borax 50
Fe_2O_3 10
Carbon 1 1/2.
Sulphr 1 1/2.

No 12 Shade double Color
" 3 " 1/2 Color.

1913

Sunday 24

When Glass stands
Out & no In
add K_2CO_3
or $NaCO_3$

When In & not out
add SiO_2

S	555+115	335+60	1965+20
P	435	435	1305
B	285	285	855
N	120	120	360
C	—		80
A	—		42
ag.	9		
Ni	1		— 100
K	12		

R T W P G B AU



ALOS. for the [illegible]

SiO_2	345·8	172·9	86·45
Pb_3O_4	56·8	28·4	14·2
Na_2CO_3	86·4	43·2	21·6
Cyolite	20·6	10 7/8	5 — 3 7/8
Al_2O_3	60·	30·	15·
$NaNO_3$	32·	16	8
Borax	8	4	2
$CaSO_4$.	5·	2½	1¼

12 hrs melt.

yellow

R T W P G B A

Yellow. alabaster

150 alab Batch

4 Ur.O.

445.Y.

" Yellow alb. —

to match dome light.

100 alab Batch 100

5 Chma clay. 10 10

2 Cyrlite 2½ 4

½ $CaSO_4$ ½ 1

1 or Ur.O. 1 2 or

SiO_2 218.

Pb_3O_4 145–

Borax 90

$NaNO_3$ 40

Ca_3PO_4 4

As_2O_3 3

Yellow opal one

200 g above Blch

½ Un_2O.

R T W P G B

Qu 18 Brown A91

S. 63
P 36
B. 24
$NaNO_3$ 10
Na_2CO_3 1 + H
Fe_2O_3 7
MnO_2 5

was too hard added H Na_2CO_3
made it O.K

R T W P G B

All Blue for Casing -
200 of Antwhite Called
200 Grms of CoO.

Celeste Blue / 201X1

F Btch 260

$CuO + \frac{1}{5}\frac{1}{2}\ Na_2CO_3$

Dorg. Blue for Hard.

SiO_2	54½
Pb.	36½
$NaNO_3$	19.
CaO	½
Na_2CO_3	8¼
Ca_3PO_4	8
As_2O_3	1½

R T W P G

Black

260 Siftings
50 Btel
6 MnO2

Flint Brown or Umber

F Batch 200

22 Fe_2O_3 4 +3 Na_2CO_3

21 MnO_2 1½ + SiO_2

Pale Blue to wood
with above.

F Batch 100

SiO_2 10

24 $Co.O.$ 20 Grms.

10 Bat + 5 Na_2CO_3 + H

+10 SiO_2

R T W P G

200 Btd
10 Gm CoD
10 NarCos

100 Btd
20 CoD
5 NarCos

Brown for Hut. (F3)

SiO_2	63 3/4
Chrom	15 —
Na_2CO_3	18 + 5
$NaNO_3$	5 —
Borax	4
MnO_2	4 1/2
Fe_2O_3	16 1/2

did not stand added 6 Na$_2$CO$_3$

R T W P G

Blue & work with this

100 Blue Cullet
30 Batch
250 grams CoO
5 Na_2CO_3

1 G.

added 5 Na_2CO_3
5 Batch
this was worse
added 5 Batch
10 SiO_2 & 25 Gr CoO

F Batch 260
F Cullet. 32
Cr_2O_3 2.
CuO. 3.
Na_2CO_3. 8
SiO_2 5

Olive Green Light from at No 1
3 weighs of 260 above Cullet.
1 " " F Cullet.

R T W P G

Ind. Pd..

4 G № 7.

SiO_2	200
Pb_3O_4	85—
Na_2CO_3	75—
$NaNO_3$	15—
CuO	10 or
Cr_2O_3	6 or
$BaCO_3$	6 el
Borax	5-11

Chrome Green.

SiO_2	60	100 R 235-
Pb_3O_4	36	of Bleb & Calcl.
B.	24	& added 2 Na_2CO_3
$Na \cdot NO_3$	10	OK no out.
K_2CO_3	26	
CaO	3	
Cr_2O_3	1	

136

did not stand in Feb 7th 1911
added 2 Na_2CO_3 to above

R T W P

G 401 BE cgm.

SiO_2	342	171 — 171	1
Na_2CO_3	150	75 — 75	6
$NaNO_3$	30	15 — 15	7
$CaCO_3$	70	35 — 35	13
CuO	5	2½ — 2½	43
K_2CrO_4	4	1 Cr_2O_3 — 2	33

MnO 1½ gm
Rutile 2 ch.

R T W P

Royal Paper.

234 X

4 heights of 260. F Softings
1 " " 260 " Blch
12 MnO2.

R T W P

Pomona. Green

SiO_2	250 lb	300
Na_2CO_3	130	130
$NaNO_3$	50	50
Pb_3O_4	6	10
$BaCO_3$	8	10
Cr_2O_3	3	3
CuO	9 oz	9 oz

R T W

N. White / 420 x 11

S.	700	— 350	700
P.	200	— ~~100~~ 50	~~100~~ 90
N	170	— 85	170
	40	20	40
NO_3			6
B	6	— 3	
CaF_2	85	42½	100
Zel	85	42½	100
MnO_2	1½	— ¾	.1
Cyolite	3	1½	3

R T W

F. 17. 260

F Soluble [F 260]

F Btch 300

20. Ca_3PO_4 20

28. As_2O_3 10

6. Na_2CO_3 28. +5 ~~35~~ ~~+5~~

1. SiO_2 71

Stood out not to added

5 Na_2CO_3 made O.K

Nov 1916

did not stand in Jel 7 1/2

added 5 Na_2CO_3 to

445 gal on O.K

R T

730
80
650
190
760

4

Zopar..

(44)

820 Blch 4 1/4 hr O.

410 — 2 ℓ.

260 — 1 ℓ

R T

dark Topaz

260 Hm 1 Btch

$2\frac{1}{2}$ WO

$\frac{1}{2}$ MnO_2

---

for Schmidt

---

trial for Golden Topaz
as F.A.Co sample.

100 lbs of Topaz 13 Tel
1/2 " " Ca_2O (44)
1 1/2 " Fe_2O_3 (22)
1/2 Mn_2O (21)

N.G. looks much like
amber with a dark cast
try Cd.S.

R

April 1919

Standard 1 m 189.

added 108

+ 10 el Narcos 7 OK

50

6

4 1/2

1 1/2

3/4

309 am.

410 3/4

Au. Ruby.

1	SiO_2	63
3	Pb_3O_4	36
9	Borax	24
5	KNO_3	10
4	K_2CO_3	2
42	Reg Ant	1 1/2
31	Sn_2O_3	1/2
21	MnO_2	1/4
37.	Au	10 Grams

Did not stand with Calcite
added 20 SiO_2 OK

R

395
40
355

Ruby for Flint

SiO_2	95-
Pb_3O_4	85-
K_2CO_3	45- or
Rg Ant.	3·2
Sn_2O_2	1-0-16
MnO_2	13·8
Au	28 Grains

Sel Ruby S.R.20

SiO_2	106	54
Na_2CO_3	46	26
ZnO	10	6
Cryolite	4	
CdS	24 gr	
Sel	6 gr	

Has turned fine transcendent Red made Rases Stood well

— 278 A

[illegible]	108	27
Na_2CO_3	52	26
$BaCO_3$	20	10
[illegible]	6	2½
[illegible]	3	1½
[illegible]	30	20

244 Cd S. yellow

		A	B
SiO_2	54	108	[illegible]
Na_2CO_3	26	52	7[illegible]
$BaCO_3$	10	20	30
[illegible]	3	3	3
Cd S	1.5	1.5	1.5
	Yellow	[illegible]	[illegible]

Added 1½ [illegible]

[illegible] A.B.