


Straightening

Things to think about:
Temperature of the piece,
temperature of the punty,
direction of the force
being applied by the
tweezers


Step 1

Catch the lip or front of the piece to minimize the torque on the punty, then rotate pipe quickly to see the angle of the bottom of the piece




Step 2

Make the bottom of the vessel perpendicular to the floor




Step 3

Put high side on top



Step 4



This action makes the back of the piece slide down the punty, centering the piece

Step 5

Repeat steps 2-4 quickly until straight

NOTE:

While transitioning from step 4 back to step 2, do not remove the tweezers from the lip

